

# ATTACHMENT A

## Unanticipated Repairs for FY 2018-19

| Invoice Month | Amount       | Equipment No. | Description   |
|---------------|--------------|---------------|---|
| July-18       | \$ 17,000.00 | 0016          | <b>Cause:</b> Machine not spraying water.<br><b>Resolution:</b> Install new pump, motor, and water lines.                                 |
| August-18     | \$ 67,000.00 | 0102          | <b>Cause:</b> Undercarriage is worn and has exceeded its useful life.<br><b>Resolution:</b> Replace undercarriage.                        |
| August-18     | \$ 50,000.00 | 0108          | <b>Cause:</b> Engine overheating. Sludge in cooling system.<br><b>Resolution:</b> Minor engine rebuild and cooling system reconditioning. |
| September-18  | \$ 98,000.00 | 0107          | <b>Cause:</b> Transmission failed.<br><b>Resolution:</b> Rebuild transmission.  |
| October-18    | \$ 69,000.00 | 0005          | <b>Cause:</b> Undercarriage is worn and has exceeded its useful life.<br><b>Resolution:</b> Replace undercarriage.                        |
| Pending       | \$ 65,000.00 | 0016          | <b>Cause:</b> Engine and final drive failure.<br><b>Resolution:</b> Rebuild engine and final drive.                                       |
| Pending       | \$ 16,000.00 | 0128          | <b>Cause:</b> Reaction arm bad. Normal wear and tear.<br><b>Resolution:</b> Replace reaction arm.   |

**Total \$ 382,000.00**